Joto Pneumatic Large Format Heat Press (XSTM-68)

Model No.: E-HP-JLF-XSTM-68

OPERATOR'S MANUAL







For Use By Qualified Personnel Only

When using your Heat Press, basic precautions should always be followed, including the following:

Read all instructions.

Use heat press only for its intended use.

Always keep the heat press dry. Do not get the heat press wet to reduce the risk of electric shock. Do not store heat press in a wet/ damp area.

Never pull cord to disconnect the power. Instead, grasp plug and pull to disconnect from power outlet.

Make sure you protect the power cord by keeping it away from hot surfaces. Avoid placing objects on top of the cord. This could cause damage to the cord and could be a fire hazard risk.

Do not operate heat press with a damaged cord or if the equipment has been damaged. To prevent risks of injury, please do not disassemble or attempt to repair the heat press by yourself if you are not qualify to do so. Instead, call or take it to a qualified service person for examination and repair. Incorrect assembly or repair could increase the risk of fire, electric shock, or injury to persons when the equipment is used.

If heat press being used by or near children, please make sure that it is supervised. Do not leave equipment unattended while connected.

Metal parts on the press can become hot. Avoid touching the hot metal parts to prevent burns. Proceed with caution when using the heat press.

To reduce the likelihood of circuit overload, Joto recommends to use a dedicated circuit if possible.

Make sure that the cord is safely secured so it cannot be pulled or tripped over.

If you need to use an extension cord, make sure you use a 20 amperage rated cord. Cords rated below 20 amperage can overheat. Make sure that the extension cord is safely secured so it cannot be pulled or tripped over.

Note: This heat press should not be set to exceed 400°F (200°C). Setting the press temperature to above 400°F (200°C) may cause a fire hazard.



PLEASE KEEP THE BOX THAT YOUR HEAT PRESS ARRIVED IN, ALONG WITH ALL ORIGINAL PACKAGING.

Congratulations on your purchase of a Joto Pneumatic Large Format Heat Press XSTM-68! In order to work professionally with the machine and start production, please make sure you read this manual carefully.

Reproduction of this manual requires written consent from Joto. Errors and amendments of technical details excepted, all rights reserved. Joto is not liable for any direct or indirect damages caused by the use of this product.

Table of Contents

| Safety2 |
|-----------------------------|
| Introduction3 |
| Heat Press Overview4 |
| Machine Parts Diagram5 |
| Setting Up Your Heat Press6 |
| Operating Instructions7 |
| Maintenance8 |
| Heat Pressing Guide 9-10 |
| Schematic Diagram11 |
| Expanded View 12-13 |
| Circuit Diagram14 |
| Warranty15 |
| Contact16 |
| |

Heat Press Overview



Technical Specs

Model No.: Machine Type:

Machine Size:

Heat platen Size:

Max Print Area:

Controller

Printable Materials:

Voltage:

Power:

Time Range: Maximum Temp:

Packing Size:

Gross Weight:

Automatic, Double Station 123.22" x 83.07" x 61.02"

E-HP-JLF-XSTM-68

(3130 x 2110 x 1550mm)

48" x 68" (120 x 170cm)

Up to 48" x 68" (120cm x 170cm)

GY-06 Digital Controller

Up to 6.96" (177mm) thickness

380V/ 3 Phase

18KW, 27A


0-999 Seconds 491°F (225°C)

123.22" x 80.07" x 61.02" (3130 x 2110 x 1550mm)

2866.01 (1300kg), wooden crate

Note: This heat press should not be set to exceed 400°F (200°C). Setting the press temperature to above 400°F (200°C) may cause a fire hazard.

Machine Parts Diagram



is reached. Close and open the press to stop the beeping.

Setting Up Your Heat Press

How to adjust pressure (figure 1.1):

- 1. Connect the heat press with air compressor or air sources.
- 2. Lift up the cap of air valve as the picture four shown
- 3. Revolve the cap anticlockwise, the air pressure goes down; conunterclockwise, the air pressure goes up; when you finish the pressure adjustment, push down the cap.
- 4. Suggested air pressure is 0.6~0.8Mpa. It depends on the transfer materials.

How to Read The Display

- 1.) Turn on Heat Press, display screen will switch on
- 2.) Right side PV value = Current Temperature
- 3.) Left side PV value = Current Time
- 4.) Right side SV value = Set Press Temperature
- 5.) Left side SV value = Set Press Time

Setting Press Temperature

Press the corresponding number of SV to start. Touch the °F or °C buttons tochoose to display in °F or °C. °F stands for Fahrenheit

°C stands for Celsius

Press ENT to save and exit, CLR to clear the settings, ESC to reset.

Use keypad to set press temperature value. Press ENT to save

Note: Setting the press temperature to above 400°F (200°C) may cause a fire hazard.

Setting Press Time


Press the SV Time Value and a keypad will show up.


Press the numbers on the keypad change the value.

Press ENT to save the value.

Wait until the current

temperature is the same as the set temperature before using. The press will beep once set temperature





4#

151 152

2794

Manual

Up Plate

5#

151

149

200

HEAT START

Set Up

ON

TEMPERATURE

SV

SV

Auto

2# 3#

PV 149 152

151

Operating Instructions

Pressing a images to your substrate

- 1.) Ensure that the air supply is connected to the press.
- 2.) Turn on the Main Power Switch.
- 3.) Adjust the air pressure to 0.6-0.8Mpa. Heat platen will open automatically.
- 4.) Draw out the under plate and place the substrate on top of the under plate.
- 5.) Set the appropriate Press Temperature, and Time as per your transfer paper, transfer vinyl or sublimation instructions.
- 6.) Wait until current temperature is the same as the set temperature. Once the press has reached set temperature, place transfer material on the shirt. For Sublimation, place the paper with the image face down. For cuttable transfer vinyl, place the matte side with the transparent carrier backing facing the heat platen. For some sublimation items, the imaged transfer paper is on the bottom with image face up while the substrate is placed on top with printable side face down. If unsure, please refer to the instructions you received with your transfer materials.
- 7.) Push the green start-up switch. The platen will close automatically. The current time value will start counting down. Once the timer reaches the last 2 seconds before reaching 0, it will start to beep to warn you. It is recommended to stand clear of the press and let the auto-open feature work without obstruction. Once time reaches zero, the press will open.

Note: Once the press is closed, it cannot be opened manually until the timer reaches zero. In an emergency, you may press the red emergency stop button to force open the press. When pressing the red emergency stop button, the press will open immediately without warning. Keep hands on the heat press handle at all times during and after pressing the emergency stop button. Not securing the handle with your hands may cause injury.

8.) For most sublimation and transfer vinyl, the peel is hot. If unsure, refer to the instructions that came with your transfer materials.

CAUTION: Suitable air pressure is 0.4-0.5Mpa or 75-80Psi. Do not exceed this range as too much air pressure may damage the machine, and not enough air pressure will not allow the heat platen to work properly.

Maintenance

General Maintenance

Please switch off the machine and unplug the power cord when the machine is not in use.

To protect the heat platen, do not allow any hard surface objects to be in direct contact with the platen. This includes zippers, buttons, metal sublimation items. When pressing these items, place a protective sheet between the platen and the objects.

The heat platen will cool down to the room temperature, if heat press is not used for more than 30 minutes.

The heat-releasing fan will automatically starts when the temperature of heat platen reaches 80 degree C (176 degree F). It helps to reduce the temperature of electrical parts and prolong the service life of them.

Please add the lubrication oil regularly on the joints. To prolong the life of your heat press. The frequency will depend on how often you use your machine.

Always check to ensure there is enough lubricating oil in the Cylinder.

Note: This heat press should not be set to exceed 400°F (200°C). Setting the press temperature to above 400°F (200°C) may cause a fire hazard.



If your heat press stops working, please contact Joto at 1-800-565-5686 so we can help you troubleshoot.

Transfer Vinyls

MultiCut One-4-All

Temperature: 265°F Time: 3-5 seconds Peel: Warm (Cotton)

MultiCut New Flock

Temperature: 310-330°F Time: 15 seconds Peel: Warm

MultiCut Nylon

Temperature: 300-305°F 1st Press Time: 3-4 seconds 2nd Press Time: 10-15 seconds







MultiCut Premium

Temperature: 310-330°F Time: 45 seconds Peel: Warm/Cool

MultiCut Lustre

Time: 15-20 seconds

MultiCut Style

Time: 15-20 seconds

Peel: Hot to Cold

Peel: Hot to Cold

Temperature: 310-330°F

Temperature: 310-330°F







For more instructions, please visit our website at www.jotoimagingsupplies.com/support/how-to-library/instructions.html

Transfer Papers

CL TrimFree Dark

(REQUIRE A WHITE TONER PRINTER)

Temperature: 310°F 1st Press Time: 120 seconds 2nd Press Time: 30 seconds

Inkjet Light Temperature: 350-365°F Time: 20 seconds Peel: Warm



CL TrimFree Light

Temperature: 330°F Time: 30 seconds Peel: Warm (5-10 seconds)





Inkjet Dark Temperature: 375°F Time: 20-25 seconds Peel: Cool



For more instructions, please visit our website at www.jotoimagingsupplies.com/support/how-to-library/instructions.html

www.jotoimagingsupplies.com 1-800-565-5686 Blaine, WA | Las Vegas, NV | Antioch TN | Coquitlam, BC | Brampton, ON

Heat Pressing Guide

Sublimation Items

Sublimatable Ceramic Tiles

Temperature: 400°F Time: 360-420 seconds Peel: Hot Method: Substrate face down Image face up



iLumipiX Photo Panels

Temperature: 400°F Time: 65-150 seconds

Time may varied based on size. Scan the QR code on the left for instructions or visit our website.

Sublimatable Towels

Temperature: 360°F Time: 120 seconds Peel: Hot Method: Substrate face up Image face down



Sublimatable Pillows

Temperature: 375°F Time: 45 seconds Peel: Immediate Method: Substrate face up Image face down



Sublimatable Slates

Temperature: 360°F Time: 480 seconds Peel: Immediate Method: Substrate face up Image face down



For more instructions, please visit our website at www.jotoimagingsupplies.com/support/how-to-library/instructions.html

Porcelain Ornaments

Temperature: 400°F Time: 180-240 seconds Peel: Hot Method: Substrate face down Image face up



Coasters with Cork Bottom


Temperature: 400°F Time: 75 seconds Peel: Hot Method: Substrate face up Image face down

Pot Holder


Temperature: 360°F Time: 120 seconds Peel: Immediate Method: Substrate face up Image face down



Schematic Diagram



Expanded Diagram




Expanded Diagram

| Serial No. | Part Name | Qty |
|------------|---|-----|
| 1 | Quick Connector | 1 |
| 2 | Throat Hoop | 4 |
| 3 | Filter | 1 |
| 4 | Ø18 x 12 Air Pipe - 6m | 1 |
| 5 | Throttle Valve | 6 |
| 6 | Ø12 x 8 Air Pipe - 1.5m | 1 |
| 7 | Solenoid Valve Assembly | 1 |
| 8 | Cylinder | 2 |
| 9 | Cylinder Connection | 2 |
| 10 | Lower Frame Connector | 10 |
| 11 | Lower Frame | 1 |
| 12 | Lower Frame Panel | 1 |
| 13 | Ø12 Pnuematic quick connect | 6 |
| 14 | Female Tee Connecter | 2 |
| 15 | Electric Box | 1 |
| 16 | M16 Adjusting Foot | 4 |
| 17 | Casters | 4 |
| 18 | Frame | 1 |
| 19 | Proximity Switch | 3 |
| 20 | Proximity Switch Mounting Plate | 1 |
| 21 | Limit Glue | 4 |
| 22 | Limit Mounting Plate | 2 |
| 23 | Control Box | 1 |
| 24 | Lower Left Panel | 1 |
| 25 | Upper Left Panel | 1 |
| 26 | Hinge | 2 |
| 27 | Elecric Box Door | 1 |
| 28 | Back Lower Plate | 1 |
| 29 | Back Ventilation Panel | 1 |
| 30 | Back Upper Plate | 1 |
| 31 | Left Front Rail Plate | 1 |
| 32 | Left Back Rail Plate | 1 |
| 33 | Linear Bearings | 8 |
| 34 | Linear Bearing Mouting Plate | 4 |
| 35 | Synchronous Belt Installation Lower Plate | 8 |
| 36 | Synchronous Belt Installation Upper Plate | 8 |
| 37 | Synchronous Belt | 4 |
| 38 | Synchronous Wheel | 4 |
| 39 | Emergency Stop Switch Box | 2 |
| 40 | Front Lower Plate | 1 |

| Cardal Na | Devis Marrie | 01 |
|------------|---------------------------------------|----------|
| Serial No. | Part Name | Qty 2 |
| 42 | Tension Assembly Lower Right Panel | 1 |
| 43 | Upper Right Panel | 1 |
| 43 | | 1 |
| | Front Upper Plate | |
| 45 | Front Pass | 1 |
| 46 | Start Electric Box | 2 |
| 47 | Control Panel | 2 |
| 48 | Frame | 2 |
| 49 | Tray | 2 |
| 50 | Recycled Cotton Pad | 2 |
| 51 | Heat Resistant Felt | 2 |
| 52 | Heat Resistant Fabric 1710X1210 | 2 |
| 53 | Siliding Rail | 4 |
| 54 | Right Front Rail Plate | 2 |
| 55 | Right Back Rail Plate | 1 |
| 56 | Heat Resistant Fabric 2000x1210 | 1 |
| 57 | Heat Resistant Fabric Mounting Plate | 2 |
| 58 | Limit Column Mold Foot | 4 |
| 59 | Heat Resistance Fabric Splint Film | 2 |
| 60 | Heating Plate | 1 |
| 61 | Heating Pipe | 6 |
| 62 | Adapter Board | 1 |
| 63 | Spacer | 4 |
| 64 | Heating Plate Cover | 1 |
| 65 | Outlet | 2 |
| 66 | Positioning Post | 4 |
| 67 | Ø60 x 40 Compression Spring | 14 |
| 68 | Platen | 4 |
| 69 | Top Frame | 1 |
| 70 | Top Cover | 1 |
| 71 | Fan Mounting Flange | 1 |
| 72 | Drive Shaft Flange | 2 |
| 73 | 6003 Bearing | 2 |
| 74 | 26 Tooth Sprocket | 2 |
| 75 | 13 Tooth Sprocket | 1 |
| 76 | Transmission Shaft | 1 |
| 77 | Tension Mounting Plate | 1 |
| 78 | Transmission Reducer | 1 |
| 79 | Reducer Mounting Plate | 1 |
| 80 | Chain | 1 |

Circuit Diagram



Warranty Statement

JOTO warrants to the original purchaser JOTO's E-HP-JLF-XSTM-68 heat presses or component that such heat press or component is free from defects in materials and workmanship, subject to the limitations set forth below.

IN LIEU OF ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, WHICH JOTO HEREBY DISCLAIMS, THE OBLIGATIONS OF JOTO UNDER THIS WARRANTY ARE EXPRESSLY LIMITED TO THE FOLLOWING:

a. JOTO will repair or replace at its option, free of charge, any product, component of its products, and any component it sells separately which is installed in JOTO's heat presses, within twenty-four months and sixty months for the heating platen after shipment by same.

b. This warranty does not apply to damage incurred in shipment. Damage incurred in shipment should be reported to the designated carrier. It is the carrier's responsibility to ensure arrival in undamaged condition.

c. Service labor, when requested in connection with any of the above items covered by this warranty, will be charged for traveling expenses only.

d. This warranty applies only if the product or component proves to be defective under conditions of normal use. It does not apply to breakage or to defects resulting from accident, alteration, misuse, or improper installation.

e. This warranty does not include installation of the product or component.

f. Prior to any return of a product or component, Buyer must receive written authorization to do so from JOTO. After written authorization, Buyer shall return the defective product or component freight prepaid by the original purchaser and JOTO will ship the replacement or repaired component freight prepaid by JOTO.

g. This warranty is effective only if the product or component is installed in a location and manner prescribed by JOTO instructions and only if it is maintained in accordance therewith. This warranty shall become ineffective if the product or component is altered by anyone other than JOTO employees. JOTO neither assumes, nor authorizes any person to assume for it, any obligation or liability other than as specified herein.

JOTO WILL IN NO CASE AND UNDER NO CIRCUMSTANCES BE LIABLE FOR SPECIAL OR CONSEQUENTIAL DAMAGES, LOSS OF PROFIT OR COMMISSION, OR FOR LOSS OR DELAY IN PRODUCTION.

Without limiting the generality of the foregoing, JOTO will not be liable with respect to furnishing or delay in furnishing any product or component, the use, resale or other disposition thereof, failure to furnish the same, or any other cause. JOTO liability arising out of the supply of any product or component, its use, resale or other disposition, or out of any guarantee or warranty, express or implied, or any other cause shall in no case exceed the cost to JOTO of the product or component which JOTO has agreed to supply. All liability of JOTO with respect to any product or component shall terminate upon the expiration of the twenty-four month period described above.

-Any controversy or claim arising out of or relating to transactions or orders or breach thereof, including breach of warranty, shall be settled by arbitration in Blaine, Washington, pursuant to the rules of American Arbitration Association. Any award made against JOTO shall be limited as provided above. Judgment upon award rendered by arbitration may be entered in any court having jurisdiction thereof. However, at JOTO's option, this paragraph shall not apply to collection by JOTO of the price of any product sold or any action related thereto.

IMPORTANT

PLEASE KEEP THE BOX THAT YOUR HEAT PRESS ARRIVED IN, ALONG WITH ALL ORIGINAL PACKAGING.



Bringing images to life^m

www.jotoimagingsupplies.com Tel: 1-800-565-5686 Fax: 1-800-565-5622 Coquitlam, BC | Brampton, ON Blaine, WA | Las Vegas, NV | Antioch TN